Camp Lejeune Lead Service Line Inventory

In accordance with the Lead and Copper Rule Revisions published in the Federal Register on 15 January 2021, the United States Environmental Protection Agency (EPA) mandated that community water systems complete comprehensive Lead Service Line Inventories on or before 16 October 2024.

Marine Corps Installations East-Marine Corps Base Camp Lejeune (Camp Lejeune) completed inventories for its: Holcomb Boulevard, Hadnot Point, Marine Corps Air Station New River, Rifle Range, and Onslow Beach drinking water distribution systems. Each inventory is available to the public on the Base website and can be accessed via the following direct link URL:

https://www.lejeune.marines.mil/Offices-Staff/Environmental-Mgmt/Lead-Service-Line-Inventories/

Based on available data and records, Camp Lejeune has verified, through distribution system material surveys and desktop evaluations of Public Works Department records and Geographic Information System (GIS) records, that there is no indication of any lead service lines being installed in any of the Base's drinking water distribution systems.



Date last updated: May 30, 2024



What is the purpose of this template?

The purpose of this template is to help water systems comply with the service line inventory requirements of the January 15, 2021 Lead and Copper Rule Revisions (LCRR). This template provides fillable forms and tables for water systems to document their methods, organize their inventory, submit the initial inventory and inventory updates to the state, and document how they are making the inventory publicly available. The State of North Carolina **requires** systems to use this template for their inventory.

*This template is a modified version of the EPA Service Line Inventory Template released August 4, 2022 for use by States.

How is the template organized?

The **worksheets** in this template are color coded:

Yellow sheets are instructions and background.

Dark blue sheets are templates for systems.

The **cells** in this template are also color coded:

Gray cells are background or instructions.

Light blue cells are fillable cells for systems.

Aqua cells are the required fields.

See the table below for a description of each worksheet.

Light green cells are auto populated as the **Detailed Inventory** is filled.

Template Organization		
Worksheet Type	Worksheet Name	Description
Background	Introduction	Contains introduction to the worksheet.
	Inventory Summary	For systems to provide a summary of their service line inventory, including information on ownership, inventory format, and the number of service lines for each of the four required materials classifications. Totals are automatically generated based on information entered in the Detailed Inventory worksheet.
Templates for Water Systems	Detailed Inventory	For systems to track materials for each service line in their distribution system. Each row equals one service line connecting the water main to the customer's plumbing. Separate columns track location information, the system-owned portion, the customer-owned portion, other possible sources of lead, information for assigning a tap sample tiering classification, and information for lead service line replacement (LSLR).

Inventory Summary

PWS Name: USMC LEJEUNE - ONSLOW BEACH

PWSID: NC0467048

Enter Date Last Updated:

05/30/24

Purpose of this worksheet: For water systems to provide a summary of their service line inventory, including information on ownership and the number of service lines for each of the four required materials classifications.

Part 1. General Information

1. Is this the Initial Inventory or an Inventory Update?

Initial Inventory

2a. Who owns the service lines in your system? If other, please explain below.

Split ownership between the system and the customer

Ownership is split between the system and Atlantic Marine Corps Communities (AMCC) for the on-base housing.

2b. Is there documentation that defines service line ownership in your system, such as a local ordinance? *If yes, please describe below and explain where ownership is split (e.g., property line, curb stop).*

Yes

MCB Camp Lejeune owns the water mains and AMCC assumes responsibility for the service lines immediately off of the main.

3a. Describe when lead service lines were generally installed in your system.

According to previously conducted material surveys, MCB Camp Lejeune has never had lead service lines installed in its drinking water distribution systems.

3b. When were lead service lines banned in your system? Reference the state or local ordinance that banned the use of lead in your system.

Not applicable

4. Do you have lead goosenecks, pigtails or connectors in your system?

Yes

5. What is your overall level of confidence in the inventory (*i.e.*, "Low", "Medium", or "High.") Please explain your rationale below.

High

MCB Camp Lejeune previously completed a comprehensive distribution system material survey in 1995, completed additional surveys in the mid-2000s, and currently maintains a robust GIS system that is continuously updated by Base GIS staff.

Part 2. Inventory Summary Table¹

The classifications generated in the Column "Entire Service Line Material Classification" (Column X) from the Detailed **Inventory** will be used to calculate the total number of service lines for each of the four material classifications below. Lead: Any portion of the service line is known to be made of lead.² Galvanized Requiring Replacement (GRR): The service line is not made of lead, but a portion is galvanized and the system is unable to demonstrate that the galvanized line was never downstream of a lead service line. 0 Non-Lead: 263 Lead Status Unknown: The service line material is not known to be lead or GRR. For the entire service line or a portion of it (in cases of split ownership), there is not enough evidence to support material classification. 0 TOTAL 263 Notes ¹ This summary table is for reporting material for the entire service line connecting the water main to the customer's plumbing. See the Classifying SLs worksheet for additional guidance on assigning a materials classification to the entire service line when ownership is split. Remember that systems must track the system-owned and customer-owned portions separately in their inventory. ⁴A lead-lined galvanized service line is consistent with the definition of an LSL under the LCRR ("a portion of pipe that is made of lead, which connects the water main to the building inlet") (40 CFR §141.2) and must therefore be classified in the inventory as an LSL. Do NOT, however, count non-lead service lines with a lead gooseneck or pigtail as lead service lines unless required by your

state.

5/30/2024

Purpose of this worksheet: To allow water systems to track materials for each service line in their distribution system.

											completed	Inventory.																		
	Location Inform	ation							System	-Owned Portion								Customer-O	wned Portion	n				Other Potent	ial Sources of I	Lead	Additional	Information to	Assign Tap Monitoring Tiering	Lead Service Line Replacement (LSLR)
Unique Service Line ID	Street Address	ther Location Identifier	Sensitive Population? (Yes/No) Disac tage Neigh hoo (Yes/	dvan ed nbor od? No) Cla	stem-Owned Portion ervice Line Material assification	f Non-Lead in Column G, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size	Basis of Mat	erial Classificatio	on Was the Service Line Material Field Verified?		Line Material Was Verified: Enter the Dat of Field Verification	e Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Lin Field Ver Describe the Field Verification Method			Entire Service Line Material Classification	Is there a Lead Connector?	OtherIs thereFittingLeadEquipSolder inConnthetoServiceServiceLine?LineCon	cribe her gs and oment ected the vice that tain ead	Building Type onnected Service Line	Point-of- Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban Generally 1986 - 1988)?	Date of System- owned LSLR Date of Customer- owned LSLR
A Unique ID is recommended for each service line.	Water systems must tra- of all service lines in the inventory. For the public version, location iden required for lead and requiring replacement. does not use address location identifier, other include GPS coordinate intersection, block, or of specify service line	heir internal cly accessible ntifiers are galvanized If the system ses for their options could es, landmark, ther details to	sensitive subpopulatio n, e.g., day care, school, multifamily nome. If Yes- Other, describe in	tion et te labili subcl f eline other	op-down list includes commended classifications. "Non-Lead er", describe in Notes field	know. Used to determine if service line is galvanized	Date, year, or estimated date range when the	Diameter in inches	Select option If "Other," de	from drop down lis scribe in the Note field		Select option from drop down list. I "Other," describe the Notes field	If verification or	including	Drop-down list includes recommended subclassifications. If non-lead other, describe in Notes field.	estimated date range when the service line	Diameter	Select option from drop down list. If "Other," describe in the Notes field	Select Yes	Select option from drop down list. If "Other," describe in the Notes field	Enter approximate date of field verification or date that record was updated	Can use this field for documenting additional relevant information, including when classification changes.	Auto-filled list includes four required service line classifications of Lead, Non-lead, Galvanized Requiring Replacement, or Unknown	or pigtail where the water main	Select Yes, No,	kflow nter or eter aining	Note: This ir		y be helpful for identifying lead tap ring locations.	
{AB3890B4-16E4-41FA-B836- 1C332286230E}	34.6151084899902, - 77.2417602539062		No No	o Non	n-lead - Plastic	No	4/1/2015	6	Service line d	ameter is > 2 inche	s No				Non-Lead - Plastic								Non-Lead							
{9960EDF7-EDD5-4C93-A72F A1FADB21A912}	- 34.6131401062011, - 77.2487640380859		No No	o Non	n-Lead - Plastic	No	4/1/2015	6	Service line d	ameter is > 2 inche	s No				Non-Lead - Plastic								Non-Lead							
{54207E9E-7CC2-4F83-8784- F3D8E7545801}	34.6131401062011, - 77.2487640380859		No No	o Non	n-Lead - Plastic	No	4/1/2015	6	Service line d	ameter is > 2 inche	s No				Non-Lead - Plastic								Non-Lead							
{CD702543-CC99-4230-858B- 8C127D9CBF3E}	34.608959197998, - 77.2568435668945		No No	o Non	n-Lead - Plastic	No	4/1/2015	6	Service line d	ameter is > 2 inche	s No				Non-Lead - Plastic								Non-Lead							
{B79EB3B6-2437-4C73-95D4- 34DA02FA9B49}	- 34.604923248291, - 77.2645874023437		No No	o Non	n-Lead - Plastic	No	4/1/2015	6	Service line d	ameter is > 2 inche	5 No				Non-Lead - Plastic								Non-Lead							
{41DEC336-D4D5-4E3B-A9CD E6A77BC3D44C}	- 34.6011428833007, - 77.2719345092773		No No	o Non	n-Lead - Plastic	No	4/1/2015	6	Service line d	ameter is > 2 inche	s No				Non-Lead - Plastic								Non-Lead							
{79F6EAED-4D3E-4023-915F- 0DC8D0B5C9A2}	34.6011428833007, - 77.2719345092773		No No	o Non	n-Lead - Plastic	No	4/1/2015	6	Service line d	ameter is > 2 inche	s No				Non-Lead - Plastic								Non-Lead							
{EDEC4073-650B-424A-8991- B474AF3434A3}	34.6011428833007, - 77.2719345092773		No No	o Non	n-Lead - Plastic	No	4/1/2015	6	Service line d	ameter is > 2 inche	s No				Non-Lead - Plastic								Non-Lead							
{237B6698-6027-4A78-806D- 610B6D7A94C9}	34.5888404846191, - 77.2860946655273		No No	o Non	n-Lead - Plastic	No	4/1/2015	6	Service line d	ameter is > 2 inche	s No				Non-Lead - Plastic								Non-Lead							
{A282AB18-D840-4C36-865C- 345BF9FE64DB}	- 34.5827827453613, - 77.286376953125		No No	o Non	n-Lead - Plastic	No	4/1/2015	6	Service line d	ameter is > 2 inche	5 No				Non-Lead - Plastic								Non-Lead							
{A443D144-BC86-41C2-B921- A95A9400C259}	- 34.5827827453613, - 77.286376953125		No No	o Non	n-Lead - Plastic	No	4/1/2015	6	Service line d	ameter is > 2 inche	s No				Non-Lead - Plastic								Non-Lead							
{28D01FA9-40F2-4AC4-9D22- 1116465AB089}	- 34.6265716552734, - 77.2342834472656		No No	o Non	n-Lead - Plastic	No									Non-Lead - Plastic	4/1/2015	2	Installation date after lead ban	No				Non-Lead							
{722246F3-5CA5-46EB-B9FD- E2A3109D0992}	34.6265716552734, - 77.2342834472656		No No	o Non	n-Lead - Plastic	No									Non-Lead - Plastic	4/1/2015	2	Installation date after lead ban	No				Non-Lead							
{862F7A83-5C82-4639-A08D- 71440B546B6F}	34.5828, -77.2864		No No	o Non	n-Lead - Plastic	No	4/1/2015	6	Service line d	ameter is > 2 inche	s No				Non-Lead - Plastic								Non-Lead							
{A430BC47-2A5C-4E59-84B9- 5DABF69B2A06}	34.6205, -77.2366		No No	o Non	n-Lead - Plastic	No	4/1/2015	6	Service line d	ameter is > 2 inche	s No				Non-Lead - Plastic								Non-Lead							

Important Instructions: Each row in this worksheet represents one service line connecting the water main to the customer's plumbing. The worksheet includes required and recommended elements; the columns with the aqua shading are required by the LCRR. The green column is a required, auto populated field that will update as systems provide system-owned and customer-owned service line material classification information. Column H is used in the green column calculation to determine if the customer-owned portion of the service line is galvanized requiring replacement. If column H is blank and the customer-owned portion is galvanized, the entire line will be classified as galvanized requiring replacement. Important notes for each column are in Row 13; also see the Template Instructions worksheet for detailed instructions. Remove provided examples before submitting your completed inventory.

{33EF4B41-D04A-461D-A167- CEFD71A11F16}	34.6266, -77.2343	No No	Non-Lead - Plastic	No 4/1/2015 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{E3CA211B-EF69-4671-BE87- 31BE890C102D}	34.5727, -77.2674	No No	Non-Lead - Plastic	No 1/1/1996 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{DB4085B4-7AF8-4ED6-BD4B 62A469B2FC0D}	34.564, -77.2781	No No	Non-Lead - Plastic	No 1/1/1996 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{EB93C186-23EB-487D-9F2A- E9566BE4D682}	34.5706, -77.2757	No No	Non-Lead - Plastic	No 1/1/1996 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{7371CBF6-A665-433B-B81A- 6BE9C96D70AB}	34.5765, -77.2814	No No	Non-Lead - Plastic	No 4/1/2015 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{DC488E8B-4B86-42C3-9D3C- 04111D814BF1}	34.5727, -77.2674	No No	Non-Lead - Plastic	No 1/1/1996 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{E87FE77B-3125-43CF-AD7B- CC718B654EB1}	34.5706, -77.2757	No No	Non-Lead - Plastic	No 1/1/2000 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{FD69709C-39B9-4144-94BA- B361FCB77C6A}	34.6131, -77.2488	No No	Non-Lead - Plastic	No 4/1/2015 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{51273A2F-94B4-4A35-BE12- 97342B7426BC}	34.609 <i>,</i> -77.2568	No No	Non-Lead - Plastic	No 4/1/2015 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{09A6198C-3296-48EB-9F99- 894DAE09D8BA}	34.6205, -77.2366	No No	Non-Lead - Plastic	No 4/1/2015 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{740C1F4A-F50D-429F-B81C- ACC2E2AC9020}	34.5765, -77.2814	No No	Non-Lead - Other	No 6 Service line diameter is > 2 inches No	Non-Lead - Other		Non-Lead	
{37A922A4-413D-4E6C-9913- E29D3B15D6F9}	34.5828, -77.2864	No No	Non-Lead - Plastic	No 4/1/2015 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{26083E15-A6B2-4BBB-A756- F6BFACE1467F}	34.5727, -77.2674	No No	Non-Lead - Other	No 1/1/1996 6 Service line diameter is > 2 inches No	Non-Lead - Other		Non-Lead	
{F0532CF8-D228-4877-951C- C92BAD54873F}	34.6049, -77.2646	No No	Non-Lead - Plastic	No 4/1/2015 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{755441DE-1DB2-44D5-BABA A388FE5FF852}	34.564 <i>,</i> -77.2781	No No	Non-Lead - Other	No 1/1/1996 6 Service line diameter is > 2 inches No	Non-Lead - Other		Non-Lead	
{4AB2694A-8070-4E10-8A94- C9894AFF6134}	34.6011, -77.2719	No No	Non-Lead - Plastic	No 4/1/2015 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{CAB341C0-F4A3-4CA1-BCF4- 6EC8F163BE5D}	34.5979, -77.2781	No No	Non-Lead - Plastic	No 4/1/2015 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{ECEB88B6-A0DD-43FC-8682- 53C5CEAD0EE7}	34.5727, -77.2674	No No	Non-Lead - Plastic	No 1/1/1996 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{13DF97CB-D278-4125-AEA6- 5340812D68AF}	34.5765, -77.2814	No No	Non-Lead - Plastic	No 4/1/2015 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{1428479C-C034-431A-AB9B- 2AC2BC83EE6C}	34.5727, -77.2674	No No	Non-Lead - Plastic	No 1/1/1996 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{40E1C404-CDA0-4FDD-B343- 36EFB19C5D12}	- 34.6131, -77.2488	No No	Non-Lead - Plastic	No 4/1/2015 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	
{2CD141A2-2D56-4F69-9F01- F686E5BB7CE0}	34.5591, -77.2855	No No	Non-Lead - Plastic	No 1/1/1996 6 Service line diameter is > 2 inches No	Non-Lead - Plastic		Non-Lead	

{FB05CDF4-2B91-4425-95DF- 7DB61D338868}	34.5888, -77.2861	No No	Non-Lead - Plastic	No 4/1/2015 6 Service line diameter is > 2 inches No	Non-Lead - Plastic			Non-Lead	
{4634073D-6B54-49CC-AD25- 9B810C38BD55}	34.5727, -77.2674	No No	Non-Lead - Plastic	No 1/1/1996 6 Service line diameter is > 2 inches No	Non-Lead - Plastic			Non-Lead	
{BF22A708-814C-4802-8BA2- 7117156C0D75}	34.5727, -77.2674	No No	Non-Lead - Plastic	No 1/1/1996 6 Service line diameter is > 2 inches No	Non-Lead - Plastic			Non-Lead	
{670AF889-9602-4BFD-AA53- AA83FB6CFF0C}	34.5727, -77.2674	No No	Non-Lead - Plastic	No 1/1/196 2 Installation date after lead ban No	Non-Lead - Plastic			Non-Lead	
{896F2356-4759-4108-8A12- 3E174A663280}	34.5727, -77.2674	No No	Non-Lead - Plastic	No 1/1/1996 10 Service line diameter is > 2 inches No No Image: Service line diameter is > 2 inches No Image: Service line diameter is > 2 inches No	Non-Lead - Plastic			Non-Lead	
{96A4EA8F-14A4-4733-AA46- 3AD3D483290D}	34.5765, -77.2814	No No	Non-Lead - Plastic	No 1/1/1996 6 Service line diameter is > 2 inches No Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches Image: Construction of the service line diameter is > 2 inches	Non-Lead - Plastic			Non-Lead	
{5A948375-0673-4289-97B5- 5BAB97A5288F}	34.5706, -77.2757	No No	Non-Lead - Plastic	No 1/1/1996 6 Service line diameter is > 2 inches No Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diamet	Non-Lead - Plastic			Non-Lead	
{CD491247-AC18-400B-9904- 16562DC841BB}	34.6151, -77.2418	No No	Non-Lead - Plastic	No 4/1/2015 6 Service line diameter is > 2 inches No Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diamet	Non-Lead - Plastic			Non-Lead	
{99C845F3-113E-483F-8F1E- C53A3A57BC81}	34.6011, -77.2719	No No	Non-Lead - Plastic	No 4/1/2015 6 Service line diameter is > 2 inches No Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diameter is > 2 inches Image: Comparison of the service line diamet	Non-Lead - Plastic			Non-Lead	
{A8A208A0-CC88-4725-9E5F- E29B1D8AD776}	34.6266, -77.2343	No No	Non-Lead - Plastic	Image: Second	Non-Lead - Plastic			Non-Lead	
{91403EB3-7744-4672-A6EA- 977F37DD4068}	34.5764999389648, - 77.2813873291015	No No	Non-Lead - Plastic	Image: Second state Image: Second st	Non-Lead - Plastic	4/1/2015 6 Service line diameter is > 2 inches	No	Non-Lead	
	77.2813873291015	No No	Non-Lead - Plastic	Image: Sector of the sector	Non-Lead - Plastic	4/1/2015 6 Service line diameter is > 2 inches	No	Non-Lead	
	77.2757492065429	No No	Non-Lead - Plastic	No Image: Sector of the se	Non-Lead - Plastic		No	Non-Lead	
	77.2757492065429	No No	Non-Lead - Plastic		Non-Lead - Plastic		No	Non-Lead	
	77.2757492065429	No No	Non-Lead - Plastic		Non-Lead - Plastic	after lead ban	No	Non-Lead	
	77.2757492065429	No No	Non-Lead - Plastic		Non-Lead - Plastic		No	Non-Lead	
	77.2757492065429	No No	Non-Lead - Plastic		Non-Lead - Plastic		No	Non-Lead	
{6C167E54-4BB2-4D45-80E6- B2C79CDF3C4A} {59AFD8E1-AC64-4C56-8CDC-	77.2757492065429	No No	Non-Lead - Plastic	No No System-Owned Image: Sector of the sector	Non-Lead - Plastic		No	Non-Lead	
	77.2757492065429	No No	Non-Lead - Plastic	No Image: No System-Owned System-Owned and Customer-Owned Image: No Image: No <td>Non-Lead - Plastic</td> <td>after lead ban</td> <td>No</td> <td>Non-Lead</td> <td></td>	Non-Lead - Plastic	after lead ban	No	Non-Lead	
	77.2757492065429	No No	Non-Lead - Plastic	Image: Sector of the sector	Non-Lead - Plastic	1/1/2000 0.75 after lead ban	No	Non-Lead	
	77.2757492065429	No No	Non-Lead - Plastic	Image: Sector of the sector	Non-Lead - Plastic	after lead ban	No	Non-Lead	
	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic		Non-Lead - Plastic	1/1/2000 2 Installation date after lead ban	No	Non-Lead	

{5FC33FE7-B3B9-4FD5-924D- 47AB90E2C5DA} 34.5590515136718, - 77.2854766845703	No No	Non-Lead - Plastic	No No Column H answer is fo System-Owned Owned	d Non-Lead - Plastic	1/1/1996	2 Installation date after lead ban	No	Non-Lead	
{C5B669DE-D65A-4066-927F- 657F9A921125} 34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	No No International Column H InternationA Column H Inte	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{04478F94-2877-4F29-AE2D- 78C6C9F3F2D5} 34.5705757141113,- 77.2757492065429	No No	Non-Lead - Plastic	No No Interview of the second	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{22F96A4C-AF1B-4347-9D18- CF54B48902E2} 34.5705757141113,- 77.2757492065429	No No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{A096E455-5AFA-4522-8EC3- D606CB679130} 34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{3AC8BD95-74F4-4486-B815- F810C69B6FDC} 34.5705757141113,- 77.2757492065429	No No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{8A272EE7-82C2-4AEE-B4B6- C3CCA4312019} 34.5705757141113,- 77.2757492065429	No No	Non-Lead - Plastic	Owned	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{9A801950-B952-401A-9C23- 8DFA9A975B63} 34.5705757141113,- 77.2757492065429	No No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic	1/1/2000	2 Installation date after lead ban	No	Non-Lead	
{F379924B-4F24-4EE5-86F3- 34.5705757141113, - C4C62B215E94} 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	d Non-Lead - Plastic	1/1/2000	Service line 8 diameter is > 2 inches	No	Non-Lead	
{815CE779-A2FD-4B72-A9B5- 8F69BB839C1A} 34.5705757141113,- 77.2757492065429	No No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic	1/1/2000	Service line 8 diameter is > 2 inches	No	Non-Lead	
{F35FFD49-9E28-493C-8C84- F985F66924A7} 34.5705757141113,- 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{AC540DE2-2608-4A1A-838B- D2246F7996A8} 34.5705757141113,- 77.2757492065429	No No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic	1/1/2000	Service line 3 diameter is > 2 inches	No	Non-Lead	
{A9434934-5CBB-4055-9B7E- C31E8E082B33} 34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{4CEDDE95-4818-45CE-84D6- 436721433B29} 34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{355AACEF-2AB6-454F-821D- E7640793ED5B} 34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{14980B80-2BFE-4625-AE77- CD587A55BE71} 34.5705757141113,- 77.2757492065429	No No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{60CE0CF6-EC81-47E7-B004- 0D476A790618} 34.5705757141113,- 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{02090AD0-1D5F-4FDA-A998- C1A24F6359A5} 34.5705757141113,- 77.2757492065429	No No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{A894A6A2-AE8B-49E5-BD4D- C0A8F53367CB} 34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{F9165EFD-8F48-4804-B2D8- 2828B09FFD2B} 34.5705757141113,- 77.2757492065429	No No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	
{DCC94361-E31C-44FD-8E53- 98B87A3B4212} 34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	d Non-Lead - Plastic	1/1/2000	2 Installation date after lead ban	No	Non-Lead	
{70BD20A9-0095-4B85-813E- E46F8536633A} 34.5705757141113,- 77.2757492065429	No No	Non-Lead - Plastic	No Column H No System-Owned Image: Stress of the stres of the stress of the stress of the stres o	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No	Non-Lead	

{5257D443-33B8-4E65-80EC- A3A51A3A1273}	34.5705757141113, - 77.2757492065429	No	No Non	n-Lead - Plastic	No No Column H answer is for and Custome Owned	r ed Non-Lead - Plastic r-	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{C19306D5-EF3E-4778-BD2B- 1AADE8830238}	34.5705757141113, - 77.2757492065429	No N	No Non	n-Lead - Plastic	No No Interview of the second	ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{843B81DB-B169-4978-A286- C65B2118AED2}	34.5705757141113, - 77.2757492065429	No	No Non	n-Lead - Plastic	NO Image: Column H NO Image: Column H Image: Column H Image: Colum H Image: Column H </td <td>ed Non-Lead - Plastic</td> <td>1/1/2000</td> <td>0.75</td> <td>Installation date after lead ban</td> <td>No</td> <td>Non-Lead</td> <td></td>	ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{19D70F48-ADA6-4407-BDC7 26377F258DF8}	- 34.5705757141113, - 77.2757492065429	No N	No Non	n-Lead - Plastic	No No I I I I I I I I I I I I I I I I I	r ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{489223B3-E8F5-487D-92A7- B7B546DC1203}	34.5705757141113, - 77.2757492065429	No	No Non	n-Lead - Plastic	No No Column H answer is for and Custome Owned	ed Non-Lead - Plastic	1/1/2000	3	Service line diameter is > 2 inches	No	Non-Lead	
{1D860550-BAC7-4B9A-A9C0- E1992756E0AC}	- 34.5705757141113 <i>,</i> - 77.2757492065429	No N	No Non	n-Lead - Plastic	No No Column H answer is fo System-Own and Custome Owned	r ed Non-Lead - Plastic	1/1/2000	2	Installation date after lead ban	No	Non-Lead	
{ABF10220-8830-4199-8916- C8020CFB491A}	34.5705757141113, - 77.2757492065429		No Non	n-Lead - Plastic	Column H	r ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{9BB2AE71-5A32-4602-96AE- 3ABD96284506}	34.5705757141113, - 77.2757492065429	No N	No Non	n-Lead - Plastic	No No I I I I I I I I I I I I I I I I I	ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{5FA8236A-01EF-4BC8-BEA0- 16021FC88EB5}	34.5705757141113, - 77.2757492065429	No N	No Non	n-Lead - Plastic	Column H answer is fo	ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{9FBF8DBB-7520-439E-AB34- 66C39B6C568B}	34.5705757141113, - 77.2757492065429	No N	No Non	n-Lead - Plastic	Column H answer is fo	r ed Non-Lead - Plastic r-	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{5E2D1A78-44F1-4BC6-AA94- EB9CCDD5A510}	34.5705757141113, - 77.2757492065429	No N	No Non	n-Lead - Plastic	Column H answer is fo	r ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{E9105E65-919D-4785-9089- 9074A8B24172}	34.5705757141113, - 77.2757492065429	No N	No Non	n-Lead - Plastic	Column H answer is fo	r ed Non-Lead - Plastic	1/1/2000		Installation date after lead ban	No	Non-Lead	
{94947F86-839D-459E-B1E7- 4C176E1191A6}	34.5705757141113 <i>,</i> - 77.2757492065429	No N	No Non	n-Lead - Plastic	Column H answer is fo	ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{1640FE6A-D14E-40C0-9C73- BE409598503B}	34.5705757141113 <i>,</i> - 77.2757492065429	No N	No Non	n-Lead - Plastic	Column H answer is fo	r ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{C9035D0C-A74F-4AB2-A196- FB6D94959E84}	- 34.5705757141113, - 77.2757492065429	No N	No Non	n-Lead - Plastic	Column H answer is fo	ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{472E537E-6B03-4BDC-A1BC- 7CA969BA5A2C}	- 34.5705757141113 <i>,</i> - 77.2757492065429	No N	No Non	n-Lead - Plastic	Column H answer is for	ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{8FE6DBEA-8A38-4B44-9896- 76A0F6FA9D31}	34.5705757141113, - 77.2757492065429	No N	No Non	n-Lead - Plastic	Column H answer is fo	ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{ECFDD1B9-F255-43DC-8A62- 5B664003549C}	- 34.5705757141113, - 77.2757492065429	No N	No Non	n-Lead - Plastic	Column H answer is fo	ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{A360D7F8-6899-4785-AFCC- D5501720B78E}	34.5705757141113 <i>,</i> - 77.2757492065429	No N	No Non	n-Lead - Plastic	Column H answer is fo	ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{953790CF-657C-4298-BA7E- A72F7A2495AA}	34.5705757141113, - 77.2757492065429	No N	No Non	n-Lead - Plastic	Column H answer is fo	ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{53F65489-0464-444D-B21B- 73796EB8F4EF}	34.5705757141113, - 77.2757492065429	No N	No Non	n-Lead - Plastic	Column H answer is fo	ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	
{13A0147C-9D91-4C68-B735- CD9DCDF7AA6A}	34.5705757141113, - 77.2757492065429	No	No Non	n-Lead - Plastic	Column H answer is fo	ed Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-Lead	

{C2247A72-F6CA-4F86-86D6- 7FC43465F579}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	No No Column H answer is for and Customer Owned	d Non-Lead - Plastic -	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{E21D0A4D-1F76-4B9F-95FD- 265887B96130}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	NO Image: Column H NO Image: Column H Image: Column H Image: Column H Image: Column H<	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{E4A4D823-813D-4F21-9D73- 1C93D60D79F2}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	NO Image: Column H NO Image: Column H Image: Column H Image: Column H Image: Column H<	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{8423B6A0-85DC-48BE-AF60- FDFAD84043D2}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	No No Column H answer is for and Customer and Customer Owned	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{3E50C366-033D-4859-B095- 62142A2C9A22}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	Column H answer is for	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{EA147C6D-CE47-4CDA-8B22- 5335003B478B}	- 34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	Column H answer is for	d Non-Lead - Plastic	8/27/2012	2 Installation date after lead ban	No		Non-Lead	
{83409067-3BD6-44AF-9510- B3DB573B7279}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	Column H	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{F6EB6CCE-8E0D-436A-8D77- D3E21A30A670}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	Column H answer is for	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{A3750907-E149-4CF8-B856- 7FE9DDF9C094}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	Column H answer is for	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{F28F16E1-9E83-460B-AF1E- F0FBB93D6EF3}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	Column H answer is for	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{833C7570-58F3-4B9C-B6B7- 2CC49F8AF807}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	Column H answer is for	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{85A9959A-F3E1-4108-931F- 57C27DC4CD72}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	Column H answer is for	d Non-Lead - Plastic	1/1/2000	2 Installation date after lead ban	No		Non-Lead	
{1703B7E4-671E-4CAE-A645- 4A05E0BF25E3}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	Column H answer is for	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{7F410C72-77D7-4864-9F70- 1605ACEE7801}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	No No Column H answer is for System-Owne and Customer	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{F9F5B6FC-E688-4CC9-B9C5- 4DDC6B05A46F}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Customer	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{DAF800C5-417E-4C43-98C4- E864F1F7EC0A}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	Image: Column H and Column H A A A A A A A A A A A A A A A A A A	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{8B04DC9F-1B68-4A95-9DE2- 838A813EB905}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	Column H answer is for	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{EB40674E-969A-412F-89BC- 6C6406A6E381}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	No No Column H answer is for and Customer and Customer	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{2C57BDF4-96A8-4AFA-8335- BBF6BFD84671}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Customer	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{FFC40C97-607F-450C-A971- 28C2995DA28F}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Customer	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{26D3FB80-19D6-46E5-9772- C05EA8422E19}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Customer	d Non-Lead - Plastic	1/1/2000	0.75 Installation date after lead ban	No		Non-Lead	
{7AF4CED0-313E-4F10-8CAA- 492B62B99617}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Other	and Customer	d Non-Lead - Other		1 Previous Materials Evaluation	No	Non-leadStatus basedon previousmaterial	Non-Lead	
				Owned					surveys.		

{FE476E81-6324-4E42-9080- BC05BA89CE86}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	ed Non-Lead - Plastic	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{FC92A4BE-13C9-4215-8F2A- 5B9B3BD807BE}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	No No Interview of the second se	ed Non-Lead - Plastic	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{7DFA57A8-8E97-4724-A065- 80CAAF896751}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	ed Non-Lead - Plastic r-	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{2DC80899-1C55-4498-A83C- 2E832860B803}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	r ed Non-Lead - Plastic	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{BC69A700-38C5-48AB-95B5- 2B696444A9AA}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	ed Non-Lead - Plastic r-	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{FF9E1213-BB68-4E8A-92D3- 7F433DE6BA32}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	r ed Non-Lead - Plastic r-	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{681E5AD4-B78F-40F3-828D- 133F181F6F31}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	r ed Non-Lead - Plastic	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{2DF5175F-571D-45D0-8972- 10AEF505035F}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	ed Non-Lead - Plastic	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{DAE92DCB-1518-436B-A38F- 34C62BDCA3CE}	- 34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	and Custome Owned	ed Non-Lead - Plastic r-	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{32833E5D-0BF3-44C3-8422- A8C5C8B19386}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	No No No I I I I I I I I I I I I I I I I	r ed Non-Lead - Plastic r-	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{F9EEB35B-392E-44BB-A45A- 3068443875F9}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Other	answer is fo	ed Non-Lead - Other		1	Previous Materials Evaluation	No	Non-leadstatus basedon previousmaterialsurveys.	Non-Lead	
{0A322758-A9D6-454D-8A8F- 357641681B21}	- 34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	answer is fo	ed Non-Lead - Plastic	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{5B490A2B-69EE-4082-8E61- 4F49375C2977}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Other	answer is fo	ed Non-Lead - Other r-	4/4/2016	6 0.75	Installation date after lead ban	No	Ductile Iron; from GIS	Non-Lead	
{8759AC62-9196-463D-9E09- 818E96270E6D}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	answer is fo	r ed Non-Lead - Plastic r-	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{BFD3D605-1440-418C-9433- 0A8C0FA77E32}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	answer is fo	r ed Non-Lead - Plastic	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{B661A64C-7DBC-4C93-9624- D0356EB3F398}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	answer is fo	ed Non-Lead - Plastic r-	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{4356E44F-6593-4A93-9B9D- 15802F885D5D}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	answer is fo	r ed Non-Lead - Plastic		2	Previous Materials Evaluation	No	Non-lead	Non-Lead	
{3BB8FCEF-D0C1-4261-A812- FDCB6CE8DE1D}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Other	answer is fo	d Non-Lead - Other		1.5	Previous Materials Evaluation	No	status based on previous material surveys.	Non-Lead	
{817AF3EA-8795-475F-AA71- C801103FE679}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	answer is fo	ed Non-Lead - Plastic	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{9CFC494C-842E-4094-8510- D52D64F15962}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	answer is fo	ed Non-Lead - Plastic	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	
{FBD12F1A-BDF6-438F-93B8- CBC6189319A1}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	answer is fo	d Non-Lead - Plastic	1/1/2000		Installation date after lead ban	No		Non-Lead	
{ADF73184-0010-4868-A12B- 27DFAD931C85}	34.5705757141113, - 77.2757492065429	No No	Non-Lead - Plastic	answer is fo	d Non-Lead - Plastic	1/1/2000	0 0.75	Installation date after lead ban	No		Non-Lead	

{9E12ECF2-1319-4ABF-AFCA- 1E352587E76B}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	No No Column H answer is for and Customer Owned	d Non-Lead - Plastic -	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{EA2468BF-BA87-4318-AE85- 33A542BAAFCF}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	No N	d Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{95FA7344-C47E-4E6A-83CC- 171B9907FA94}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	No N	d Non-Lead - Plastic -	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{4F61458B-20A5-4066-A949- 211143A8C5ED}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	and Customer Owned	d Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{329312F9-0356-458B-B2C3- FDA8EF005265}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	No No I I I I I I I I I I I I I I I I I	d Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{4E7453C0-3982-4F00-B994- B62F967DC517}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{231374DC-1231-4216-BBD0- BA25603C5420}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic		d Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{C10B7F4E-7059-4FC2-AC64- C8EB0B48DC0B}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No	Non-lead	Non-Lead	
{1635EED5-FDB8-4100-B797- 3A07A3CEF0FF}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Other	answer is for	d Non-Lead - Other		1	Previous Materials Evaluation	No	status based on previous material surveys.	Non-Lead	
{1CCE4049-9DE8-405E-9538- 5DA2C32749BB}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	No N	d Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{85B7B2D6-D346-41D9-99BB 4F831658B762}	- 34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	Image: second	d Non-Lead - Plastic -	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{4ECC0027-4614-4672-BDBD- 0F623C2E93A5}	- 34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	No Image: Constraint of the system of th	d Non-Lead - Plastic	1/1/2000	2	Installation date after lead ban	No		Non-Lead	
{2F929D6D-24C3-4367-B243- 41093719ADC0}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic -	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{4401AEF0-F7B3-4103-8EA1- FBBCEF0F99BE}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	Image: second se	d Non-Lead - Plastic -	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{86907A1F-6FB1-47E0-B3D1- 4BA336A866A0}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	Image: second se	d Non-Lead - Plastic -	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{B4348617-D520-46F3-A82D- 3C441C4885A9}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic -	1/1/2000	2	Installation date after lead ban	No		Non-Lead	
{29E66255-D4A4-418C-AE24- 95472EDA0056}	34.5705757141113, - 77.2757492065429	No	No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic -	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{6148B496-8FCF-4327-AA63- 8986DD4A2A6D}	77.2757492065429	No	No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic -	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{3414DE64-32B6-4517-901D- 31BA085C15B7}	77.2673568725585	No	No	Non-Lead - Plastic	Image: second	d Non-Lead - Plastic -		0.75	Previous Materials Evaluation	No		Non-Lead	
{0F08102E-2EB4-4B8F-BDF7- 9713BA731E71}	77.2673568725585	No	No	Non-Lead - Plastic	Image: Second state Image: Second st	d Non-Lead - Plastic -	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
	77.2673568725585	No	No	Non-Lead - Plastic	Image: second	d Non-Lead - Plastic -	1/1/1996	2	Installation date after lead ban	No		Non-Lead	
{0BB61D74-7DBE-48B1-A07C 94D12F55AFD6}	- 34.572696685791, - 77.2673568725585	No	No	Non-Lead - Plastic	No answer is for System-Owned and Customer Owned Owned	d Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	

{CA6A9464-0C52-4CA4-A527- AFBE77DD93AB}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	No No I Column H answer is for System-Owner and Customer Owned	r ed Non-Lead - Plastic r-	5/9/2012	0.75	Installation date after lead ban	No		Non-Lead	
{49656068-3BE4-49F0-8543- 7C5FC2B71A0D}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	No No Column H answer is for and Customer and Customer Owned	d Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{1DDF9948-F596-4444-B964- BB27DDAE9263}	34.572696685791, - 77.2673568725585	No	No	Non-Lead - Plastic	No N	d Non-Lead - Plastic		0.75	Previous Materials Evaluation	No		Non-Lead	
{3B25D8A0-C0B1-4CEA-849C- A94A59DE63CF}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	and Customer Owned	d Non-Lead - Plastic	1/1/1996	2	Installation date after lead ban	No		Non-Lead	
{3D037E36-4EA2-4669-83CA- 191BD5C603A8}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	No No I I I I I I I I I I I I I I I I I	d Non-Lead - Plastic	1/1/1996	1	Installation date after lead ban	No		Non-Lead	
{C6762A05-AA1E-4BDE-926F- B331FDD05EC6}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic		0.75	Previous Materials Evaluation	No		Non-Lead	
{29E21421-122B-4F30-8698- EAC7C551EB56}	34.572696685791, - 77.2673568725585	No	No	Non-Lead - Other	No N	nd Non-Lead - Other -		4	Service line diameter is > 2 inches	No		Non-Lead	
{9CE234ED-2553-40F7-9CEF- A9142AA3CAA9}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{9B27E212-5093-43DB-A694- C3FF03FCCC59}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{61292EAE-51CF-4FCB-9F18- D05861412338}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic	1/1/1996	2	Installation date after lead ban	No		Non-Lead	
{EF0A0BFB-D287-44C3-93BA- 76C66C00698E}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{371B4740-CF28-47F6-B8C5- 4D926B32CC8E}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{95F531AE-D031-426C-AB47- F7B9830189CB}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{E31DF731-5E98-477D-921B- 9ACBA8047B2A}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{28DED2C2-6988-4384-910E- BF8784D286AE}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic		0.75	Previous Materials Evaluation	No	Non-lead	Non-Lead	
{EFB9814C-5E3D-486C-8C2E- FC36F274C798}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Other	answer is for	d Non-Lead - Other		0.75	Previous Materials Evaluation	No	status based on previous material surveys.	Non-Lead	
{F991170B-1B80-445F-9457- 275E99787D52}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No	Non-lead	Non-Lead	
{877A7125-F8E4-4B30-B787- 6C69FB7FE598}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Other	answer is for	d Non-Lead - Other			Previous Materials Evaluation	No	status based on previous material surveys.	Non-Lead	
{0859F8BB-3D41-4B3E-82A5- 9182F7D704AE}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic		0.75	Previous Materials Evaluation	No		Non-Lead	
{D692A05B-A008-473C-BE3C- 828F4D9E55E4}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{DC05A021-1997-40DE-8522- 77753AB89577}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{77CB9951-16AA-4E9A-9347- 20DFEFBAAA65}	34.572696685791 <i>,</i> - 77.2673568725585	No	No	Non-Lead - Plastic	answer is for	d Non-Lead - Plastic	5/9/2012	0.75	Installation date after lead ban	No		Non-Lead	

					Column H							Non-lead		
{44E4BEAF-DC8D-4D5D-8EF1 289C184B3879}	- 34.572696685791 <i>,</i> - 77.2673568725585	No N	No	Non-Lead - Other	No N	or ed Non-Lead - Oth er-	her			Previous Materials Evaluation	No	status based on previous material surveys.	Non-Lead	
{CCF334CE-C3B5-43CB-8D42- 51AA58FF9B7A}	- 34.572696685791 <i>,</i> - 77.2673568725585	No N	No	Non-Lead - Plastic	No No I I I I I I I I I I I I I I I I I	or ed Non-Lead - Plas	stic 1	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{E34A9DCE-F7C2-467B-B5D2- A0CDCF59D1CE}	- 34.572696685791, - 77.2673568725585	No N	No	Non-Lead - Plastic	No No Column H answer is f and Custom and Custom Owned	or ed Non-Lead - Plas	stic 1	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{1217925C-A52A-4226-A428- 8491FA5343EE}	- 34.572696685791, - 77.2673568725585	No N	No	Non-Lead - Plastic	Column H answer is f	or ed Non-Lead - Plas	stic		0.75	Previous Materials Evaluation	No		Non-Lead	
{49DE3521-2475-493F-8E89- 1BABF7A0C0F1}	34.572696685791 <i>,</i> - 77.2673568725585	No N	No	Non-Lead - Plastic	No No Column H No No N	or ed Non-Lead - Plas	stic 1	1/1/1996	1	Installation date after lead ban	No		Non-Lead	
{6DEEA2A9-934C-4646-9EBE- D587803C971F}	- 34.572696685791 <i>,</i> - 77.2673568725585	No N	No	Non-Lead - Plastic	and Custom	or ed Non-Lead - Plas	stic 1	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{B287D0FE-745A-47BF-9848- BB9F4BBAFA6A}	34.572696685791, - 77.2673568725585	No N	No	Non-Lead - Plastic	Image: Constraint of the system of the sy	or ed Non-Lead - Plas	stic 1	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{8CEC3688-776B-4F42-AA40- 2CFC8FE34595}	- 34.572696685791, - 77.2673568725585	No N	No	Non-Lead - Plastic	Image: Second state Image: Second state<	or ed Non-Lead - Plas	stic		0.75	Previous Materials Evaluation	No		Non-Lead	
{B7B922B0-889E-452F-B237- 4BACC2AA2491}	34.572696685791 <i>,</i> - 77.2673568725585	No N	No	Non-Lead - Plastic	Image: Market with answer is full Image: Market with answer is full	or ed Non-Lead - Plas	stic		0.75	Previous Materials Evaluation	No		Non-Lead	
{846EF114-4BCC-4376-A289- BBBDD9C548CD}	34.572696685791, - 77.2673568725585	No N	No	Non-Lead - Plastic	Image: Market with the second seco	or ed Non-Lead - Plas	stic 1	1/1/1996	1.25	Installation date after lead ban	No		Non-Lead	
{6E8A7D94-0509-42AC-A727- 4EE6EEB1F857}	- 34.572696685791, - 77.2673568725585	No N	No	Non-Lead - Plastic	Image: Market in the second	or ed Non-Lead - Plas	stic 8,	8/27/2012	2	Installation date after lead ban	No		Non-Lead	
{06649350-23FF-4B9D-9C6A- 990AB075A17C}	34.572696685791 <i>,</i> - 77.2673568725585	No N	No	Non-Lead - Other	No 6 Service line diameter is > 2 inches No And Custom		ner						Non-Lead	
{4575FBFC-AD86-46F6-9287- 104AB78DE423}		No N	No	Non-Lead - Plastic	Owned; No Owned; No Image: Column H Image: Column H </td <td>ו-</td> <td></td> <td></td> <td>0.75</td> <td>Previous Materials Evaluation</td> <td>No</td> <td></td> <td>Non-Lead</td> <td></td>	ו-			0.75	Previous Materials Evaluation	No		Non-Lead	
{56874E28-AFFC-47E8-B986-	34.572696685791, -	No N	No	Non-Lead - Plastic	No Image: Constraint of the second secon		stic		0.75	Previous Materials	No		Non-Lead	
BA15BA542503} {31219127-38B5-4031-8516-	77.2673568725585 34.572696685791, -			Non-Lead - Plastic	Image: Second state Image: Second st	er-		1/1/1996	0.75	Evaluation Installation date	No		Non-Lead	
A3645B070904} {9F6F4853-1BFB-45E7-98A0-	77.2673568725585				Image: Second	er-				after lead ban Installation date				
DDB9A0BFEE6A}	77.2673568725585	NO N	No	Non-Lead - Plastic	No System-Own and Custom Owned Owned Column H answer is f			1/1/1996	2	after lead ban	No		Non-Lead	
{4B3664CE-0A26-4DA4-AFFF- B6BB1A72132B}	77.2673568725585	No N	No	Non-Lead - Plastic		ed Non-Lead - Plas er-	stic 1	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
	77.2673568725585	No N	No	Non-Lead - Plastic	No Image: System-Own and Custom Image: System-Own and Custom Image: System-Own and Custom Image: S	ed Non-Lead - Plas er-	stic 1	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{19720650-AA4C-4E94-B5FF- B6621B66C21D}	34.572696685791 <i>,</i> - 77.2673568725585	No N	No	Non-Lead - Plastic	Image: second	ed Non-Lead - Plas er-	stic		0.75	Previous Materials Evaluation	No		Non-Lead	
{0019829B-E6D6-4DAD-9083- 84A622D69EEF}	- 34.572696685791, - 77.2673568725585	No N	No	Non-Lead - Plastic	Image: Second state Image: Second st	ed Non-Lead - Plas er-	stic 1	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{45E21773-92A2-4A04-9E4A- 7AEA22D6DFF5}	34.572696685791 <i>,</i> - 77.2673568725585	No N	No	Non-Lead - Plastic	answer is f	or ed Non-Lead - Plas er-	stic 1	1/1/1996	2	Installation date after lead ban	No		Non-Lead	
{5A2FA388-C22F-4813-9C0D- BB55333F1F43}	- 34.572696685791 <i>,</i> - 77.2673568725585	No N	No	Non-Lead - Plastic	No No System-Own and Custom Owned	or ed Non-Lead - Plas	stic 1	1/1/1996	2	Installation date after lead ban	No		Non-Lead	

{9B971DDC-E5FE-41D0-A725- 138826156A68}	34.572696685791, - 77.2673568725585	No	lo N	Ion-Lead - Plastic	and Customer Owned	Non-Lead - Plastic		0.75	Previous Materials Evaluation	No		Non-Lead	
{52889B23-84E0-48CB-8F59- 025CB1243B69}	34.572696685791, - 77.2673568725585	No	lo N	Ion-Lead - Plastic	No No Interview of the second se	Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{374FC275-9328-491F-9F9C- 7D3D7379350A}	34.572696685791, - 77.2673568725585	No N	lo N	Ion-Lead - Plastic	No No Interview of the second se		5/9/2012	0.75	Installation date after lead ban	No		Non-Lead	
{D35EBABD-CD52-4B16-85E2- E827AD950F7C}	- 34.572696685791 <i>,</i> - 77.2673568725585	No N	Jo N	Ion-Lead - Plastic	and Customer Owned	Non-Lead - Plastic		0.75	Previous Materials Evaluation	No		Non-Lead	
{1FB0E3C8-049E-499A-823B- 3CB5CD242763}	34.572696685791, - 77.2673568725585	No N	lo N	Ion-Lead - Plastic	and Customer Owned	Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{B0E33B49-09B6-4DA1-8224- 10899CF995B6}	34.572696685791 <i>,</i> - 77.2673568725585	No N	lo N	Ion-Lead - Plastic	and Customer Owned	Non-Lead - Plastic	1/1/1996	1	Installation date after lead ban	No		Non-Lead	
{C7544ACA-31CE-4C56-B58B- D08FEBB39A04}	34.572696685791, - 77.2673568725585	No N	lo N	Ion-Lead - Plastic	No No I I I I I I I I I I I I I I I I I	Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{23C78DDA-2266-4983-BD1E- 63E7E3C2265F}	- 34.572696685791, - 77.2673568725585	No N	lo N	Ion-Lead - Plastic	answer is for	Non-Lead - Plastic	1/1/1998	2.5	Service line diameter is > 2 inches	No		Non-Lead	
{19394D2F-B102-4A55-A192- 8B98C1020191}	34.572696685791, - 77.2673568725585	No N	lo N	Ion-Lead - Plastic	answer is for	Non-Lead - Plastic		0.75	Previous Materials Evaluation	No		Non-Lead	
{405DDAD3-1335-49DE-9457- 0AA444658169}	- 34.572696685791, - 77.2673568725585	No N	Jo N	Ion-Lead - Plastic	answer is for	Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{F12A4083-CACF-4706-9CFC- 60C74870E4E7}	34.572696685791, - 77.2673568725585	No N	lo N	Ion-Lead - Plastic	answer is for	Non-Lead - Plastic		0.75	Previous Materials Evaluation	No		Non-Lead	
{343473F1-D37E-43B8-BBE9- 76E96509C181}	34.572696685791, - 77.2673568725585	No N	lo N	Ion-Lead - Plastic	No N	Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No		Non-Lead	
{986E022D-8C5C-4134-B135- EA26018DF6C1}	34.572696685791, - 77.2673568725585	No N	lo N	Ion-Lead - Plastic	answer is for	Non-Lead - Plastic	1/1/1996	0.75	Installation date after lead ban	No	Non-lead	Non-Lead	
{8E1B3E20-EBFC-40AE-B2BA- 44887248282D}	34.572696685791, - 77.2673568725585	No N	lo N	Non-Lead - Other	answer is for	Non-Lead - Other			Previous Materials Evaluation	No	status basedon previousmaterialsurveys.	Non-Lead	
{4D50A86D-F2AB-4869-BBC8- DA2C5134FCD7}	- 34.572696685791, - 77.2673568725585	No N	lo N	Ion-Lead - Plastic	answer is for	Non-Lead - Plastic	5/9/2012	0.75	Installation date after lead ban	No		Non-Lead	
{AE15727C-0307-46F4-9AF5- C25376112CA4}	34.5640220642089, - 77.2780838012695	No N	lo N	Ion-Lead - Plastic	answer is for	Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{470201C1-7272-4D4B-BF8A- B6D6F3249670}	34.5640220642089, - 77.2780838012695	No N	lo N	Ion-Lead - Plastic	No N	Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{3D98204B-B630-4466-A4A8- 413897994F7D}	34.5640220642089, - 77.2780838012695	No N	lo N	Ion-Lead - Plastic	No N	Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{CD06EEF9-04A6-4E81-AC4B- 80A8296082F6}	34.5640220642089, - 77.2780838012695	No N	lo N	Ion-Lead - Plastic	answer is for	Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{16FA3A86-7815-425F-BD5C- 0CE3C15C4B57}	34.5640220642089, - 77.2780838012695	No N	lo N	Ion-Lead - Plastic	answer is for	Non-Lead - Plastic	1/1/2000	2	Installation date after lead ban	No		Non-Lead	
{5C474399-A445-4F0B-948E- 43D5A7D666E9}	34.5640220642089, - 77.2780838012695	No N	lo N	Ion-Lead - Plastic	answer is for	Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	
{4EFB1DE0-E837-4F37-8F88- 3A106775EBE7}	34.5640220642089, - 77.2780838012695	No N	lo N	Ion-Lead - Plastic	answer is for	Non-Lead - Plastic	1/1/2000	0.75	Installation date after lead ban	No		Non-Lead	

							_					
{580ABE48-18E8-4853-920D- 474526CA6488}	34.5640220642089, - 77.2780838012695	No	Non-Lead - P	Plastic	No N	rd Non-Lead - Plastic r-	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{53D27DDC-F1F0-4351-96D8- C82BE8F29E00}	- 34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	No No I I I I I I I I I I I I I I I I I	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{2020042C-72E3-44DD-92E7- C09B88C203B5}	34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	No No Interview	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{1EC8DB00-9B45-4A1C-9C6E- 0A24DD9DDD14}	34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	and Custome Owned	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{E8E97700-1A10-4218-B62B- 0C13E177E90C}	34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	No No I I I I I I I I I I I I I I I I I	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{D45E2DD4-823D-4938-9D0A 910AC4204DBE}	- 34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{45226E76-0A6E-4B14-8815- 027399E95A32}	34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is for	d Non-Lead - Plastic	1/1/199	96 1	Installation date after lead ban	No	Non-Lead	
{02BB47C4-CCCA-493E-9A02- 5DDAA7150857}	- 34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	No No System-Own and Custome Owned Column H	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{D2E055D9-194C-406E-A516- 68C1EE50ADC1}	- 34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{123C40E4-1F64-43A5-85FA- E432DDD4DEAF}	34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{6D9951E7-EBC7-42E3-B50A- 4ADADC89C22E}	34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/199	96 2	Installation date after lead ban	No	Non-Lead	
{114D5E98-12E6-48CF-8490- ED820A3FF0D9}	34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{04CF551E-24BF-44E3-BF60- 312EF30F324B}	34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/199	96 1	Installation date after lead ban	No	Non-Lead	
{BCBFCD08-3EB4-472F-871B- A12BED47A8CC}	34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{7D14046C-6B11-4956-9410- 1C7423EB3315}	34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{06E2A68D-0823-4D84-AC5B- CA04C8C3AE23}	- 34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{4A7C1896-6D1E-4357-8755- 5845A0D4490E}	34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{5DDE8D09-F2C6-4116-B280- 5B7E3BB2FDE8}	- 34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{266F99BC-CBE7-4C9B-8546- 743FBAA61A02}	34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/199	96 1	Installation date after lead ban	No	Non-Lead	
{2DB8EE47-F49E-4C1C-83AA- B82561F1D5B0}	34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{4044E78C-E416-4B43-A4C3- 30B4665BE136}	34.5640220642089, - 77.2780838012695	No No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	
{53C55968-E3BB-42B8-A927- 0F8829555972}	34.5640220642089, - 77.2780838012695	No	Non-Lead - P	Plastic	answer is fo	d Non-Lead - Plastic	1/1/200	0.75	Installation date after lead ban	No	Non-Lead	

{C0009731-8B5F-4ED9-9674- B5871AD2DD13}	34.5640220642089, - 77.2780838012695	No	No	Non-Lead - Plastic	No	Column Hanswer is forSystem-Ownedand Customer-Owned	-Lead - Plastic 1	1/1/2000	0.75	Installation date after lead ban	Non-Lead	
{50CB8DBF-28A5-43E6-9100- 07DB5668CC14}	34.5640220642089, - 77.2780838012695	No	No	Non-Lead - Plastic	No	Column Hanswer is forSystem-OwnedAnd Customer-Owned	-Lead - Plastic 1	1/1/2000	0.75	Installation date after lead ban	Non-Lead	
{CD7E9B6F-D690-43BB-8971- 84804B6D9740}	- 34.5640220642089, - 77.2780838012695	No	No	Non-Lead - Plastic	No	Column H answer is for System-Owned Non-L and Customer- Owned	-Lead - Plastic 1	1/1/2000	0.75	Installation date after lead ban	Non-Lead	
{7AC0A2F5-13A2-43A5-8BA8- E51436D1867B}	- 34.5640220642089, - 77.2780838012695	No	No	Non-Lead - Plastic	No	Column H answer is for System-Owned Non-L and Customer- Owned	-Lead - Plastic 1	1/1/2000	0.75	Installation date after lead ban	Non-Lead	
{8C1CD028-7F98-4D35-B104- 223A0F57CE79}	34.5640220642089, - 77.2780838012695	No	No	Non-Lead - Plastic	No	Column H answer is for System-Owned Non-L and Customer- Owned	-Lead - Plastic 1	1/1/2000	0.75	Installation date after lead ban	Non-Lead	
{3216E977-5839-4B74-99FC- 950720548C68}	34.5590515136718, - 77.2854766845703	No	No	Non-Lead - Plastic	No	Column H answer is for System-Owned Non-L and Customer- Owned	-Lead - Plastic 1	1/1/1996	2	Installation date after lead ban	Non-Lead	